

AGP[®]

High Endurance Concrete Grinder

G125 / G180



Instruction Manual

CE CB 



SPECIFICATIONS

Model	G125	G180
Power Input	230-240 V: 2000 W 220 V: 1700 W	230-240 V: 2300 W, 220-240 V: 2200 W
	110-120 V: 1500 W	110-120 V: 2100 W
Voltage	220-240 V ~ 50-60 Hz, or 110-120 V ~ 50-60 Hz	
No Load Speed (n ₀)	4300 - 7200 min ⁻¹	3500 - 5800 min ⁻¹
Wheel Diameter	125 mm (5")	180 mm (7")
Spindle Thread	M14	
Arbor	22.23 mm (7/8")	
Dimensions	500 x 195 x 175 mm	540 x 210 x 195 mm
Weight	4.7 kg (10.3 lb)	5.6 kg (12.3 lb)



General Safety Rules



WARNING! Read all safety warnings and all instructions. Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury.

Save all warnings and instructions for future reference.

The term “power tool” in the warnings refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

1. WORK AREA SAFETY

- a. **Keep work area clean and well lit.** Cluttered and dark areas invite accidents.
- b. **Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.** Power tools create sparks which may ignite the dust or fumes.
- c. **Keep children and bystanders away while operating a power tool.** Distractions can cause you to lose control.
- d. **Never leave the electric power tool unattended.** Only leave the machine when the tool in use has come to a complete standstill.

2. ELECTRICAL SAFETY

- a. **Power tool plugs must match the outlet. Never modify the plug in any way. Do not use any adapter plugs with earthed (grounded) power tools.** Unmodified plugs and matching outlets will reduce risk of electric shock.
- b. **Avoid body contact with earthed or grounded surfaces, such as pipes, radiators, ranges and refrigerators.** There is an increased risk of electric shock if your body is earthed or grounded.
- c. **Do not expose power tools to rain or wet conditions.** Water entering a power tool will increase the risk of electric shock.
- d. **Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool. Keep cord away from heat, oil, sharp edges or moving parts.** Damaged or entangled cords increase the risk of electric shock.
- e. **When operating a power tool outdoors, use an extension cord suitable for outdoor use.** Use of a cord suitable for outdoor use reduces the risk of electric shock.
- f. **If operating a power tool in a damp location is unavoidable, use a residual current device (RCD) protected supply.** Use of an RCD reduces the risk of electric shock.

3. PERSONAL SAFETY

- a. **Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A**

moment of inattention while operating power tools may result in serious personal injury.

- b. Use personal protective equipment. Always wear eye protection.** Protective equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.
- c. Prevent unintentional starting. Ensure the switch is in the off-position before connecting to power source and/or battery pack, picking up or carrying the tool.** Carrying power tools with your finger on the switch or energising power tools that have the switch on invites accidents.
- d. Remove any adjusting key or wrench before turning the power tool on.** A wrench or a key left attached to a rotating part of the power tool may result in personal injury.
- e. Do not overreach. Keep proper footing and balance at all times.** This enables better control of the power tool in unexpected situations.
- f. Dress properly. Do not wear loose clothing or jewellery. Keep your hair and clothing away from moving parts.** Loose clothes, jewellery or long hair can be caught in moving parts.
- g. If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.** Use of dust collection can reduce dust-related hazards.
- h. Do not let familiarity gained from frequent use of tools allow you to become complacent and ignore tool safety principles.** A careless action can cause severe injury within a fraction of a second.

4. POWER TOOL USE AND CARE

- a. Do not force the power tool. Use the correct power tool for your application.** The correct power tool will do the job better and safer at the rate for which it was designed.
- b. Do not use the power tool if the switch does not turn it on and off.** Any power tool that cannot be controlled with the switch is dangerous and must be repaired.
- c. Disconnect the plug from the power source and/or battery pack from the power tool before making any adjustments, changing accessories, or storing power tools.** Such preventive safety measures reduce the risk of starting the power tool accidentally.
- d. Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.** Power tools are dangerous in the hands of untrained users.
- e. Maintain power tools and accessories. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tool's operation. If damaged, have the power tool repaired before use.** Many accidents are caused by poorly maintained power tools.
- f. Keep cutting tools sharp and clean.** Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.
- g. Use the power tool, accessories and tool bits etc. in accordance with these instructions taking into account the working conditions and the work to be performed.** Use of the power tool for operations different from those intended could result in a hazardous situation.
- h. Keep handles and grasping surfaces dry, clean and free of oil and grease.** Slippery handles do not allow for safe handling and control of the tool in unexpected situations.

5. SERVICE

Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.

Symbols used in this manual

V.....volts

A.....amperes

Hz.....hertz

W.....watt

~.....alternating current

n_o rated speed

min^{-1} revolutions or reciprocation
per minute



.....warning of general danger



.....class II tool



.....read these instructions



.....always wear eye protection



.....always wear a dust mask.



.....always wear hearing protection



.....wear safety-approved hard hat



do not dispose of electric tools,
accessories and packaging together
with household waste material

SAFETY WARNINGS FOR CONCRETE GRINDERS

Safety Warnings Common for Grinding

- **This power tool is intended to function as a grinder. Read all safety warnings, instructions, illustrations and specifications provided with this power tool.** Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.
- **Operations such as sanding, wire brushing, polishing or cutting-off are not recommended to be performed with this power tool.** Operations for which the power tool was not designed may create a hazard and cause personal injury.
- **Do not use accessories which are not specifically designed and recommended by the tool manufacturer.** Just because the accessory can be attached to your power tool, it does not assure safe operation.
- **The rated speed of the accessory must be at least equal to the maximum speed marked on the power tool.** Accessories running faster than their rated speed can break and fly apart.
- **The outside diameter and the thickness of your accessory must be within the capacity rating of your power tool.** Incorrectly sized accessories cannot be adequately guarded or controlled.
- **Threaded mounting of accessories must match the grinder spindle thread. For accessories mounted by flanges, the arbour hole of the accessory must fit the locating diameter of the flange.** Accessories that do not match the mounting hardware of the power tool will run out of balance, vibrate excessively

and may cause loss of control.

- **Do not use a damaged accessory. Before each use inspect the accessory such as abrasive wheels for chips and cracks, backing pad for cracks, tear or excess wear, wire brush for loose or cracked wires. If power tool or accessory is dropped, inspect for damage or install an undamaged accessory. After inspecting and installing an accessory, position yourself and bystanders away from the plane of the rotating accessory and run the power tool at maximum no-load speed for one minute.** Damaged accessories will normally break apart during this test time.
- **Wear personal protective equipment. Depending on application, use face shield, safety goggles or safety glasses. As appropriate, wear dust mask, hearing protectors, gloves and workshop apron capable of stopping small abrasive or workpiece fragments.** The eye protection must be capable of stopping flying debris generated by various operations. The dust mask or respirator must be capable of filtering particles generated by your operation. Prolonged exposure to high intensity noise may cause hearing loss.
- **Keep bystanders a safe distance away from work area. Anyone entering the work area must wear personal protective equipment.** Fragments of workpiece or of a broken accessory may fly away and cause injury beyond immediate area of operation.
- **Hold the power tool by insulated gripping surfaces only, when performing an operation where the cutting accessory may contact hidden wiring or its own cord.** Cutting accessory contacting a "live" wire may make exposed metal parts of the power tool "live" and could give the operator an electric shock.
- **Position the cord clear of the spinning accessory.** If you lose control, the cord may be cut or snagged and your hand or arm may be pulled into the spinning wheel.
- **Never lay the power tool down until the accessory has come to a complete stop.** The spinning wheel may grab the surface and pull the power tool out of your control.
- **Do not run the power tool while carrying it at your side.** Accidental contact with the spinning accessory could snag your clothing, pulling the accessory into your body.
- **Regularly clean the power tool's air vents.** The motor's fan will draw the dust inside the housing and excessive accumulation of powdered metal may cause electrical hazards.
- **Do not operate the power tool near flammable materials.** Sparks could ignite these materials.
- **Do not use accessories that require liquid coolants.** Using water or other liquid coolants may result in electrocution or shock.

Kickback and related warnings

- Kickback is a sudden reaction to a pinched or snagged rotating wheel, backing pad, brush or any other accessory. Pinching or snagging causes rapid stalling of the rotating accessory which in turn causes the uncontrolled power tool to be forced in the direction opposite of the accessory's rotation at the point of the binding. For example, if an abrasive wheel is snagged or pinched by the workpiece, the edge of the wheel that is entering into the pinch point can dig into the surface of the material causing the wheel to climb out or kick out. The wheel may either jump toward or away from the operator, depending on direction of the wheel's movement at the point of pinching. Abrasive wheels may also break under these conditions. Kickback is the result of power tool misuse and/or incorrect operating procedures or conditions and can be avoided by taking proper precautions as given below.
- **Maintain a firm grip on the power tool and position your body and arm to allow you to resist kickback forces. Always use auxiliary handle, if provided, for maximum control over kickback or torque reaction during start-up.** The operator can control torque reactions or kickback forces, if proper precautions are taken.

- **Never place your hand near the rotating accessory.** Accessory may kickback over your hand.
- **Do not position your body in the area where power tool will move if kickback occurs.** Kickback will propel the tool in direction opposite to the wheel's movement at the point of snagging.
- **Use special care when working corners, sharp edges, etc. Avoid bouncing and snagging the accessory.** Corners, sharp edges or bouncing have a tendency to snag the rotating accessory and cause loss of control or kickback.
- **Do not attach a saw chain woodcarving blade or toothed saw blade.** Such blades create frequent kickback and loss of control.

Additional safety instructions for grinding

- **Use only wheel types that are recommended for your power tool and the specific guard designed for the selected wheel.** Wheels for which the power tool was not designed cannot be adequately guarded and are unsafe.
- **The grinding surface of the centre depressed wheels must be mounted below the plane of the guard lip.** An improperly mounted wheel that projects through the plane of the guard lip cannot be adequately protected.
- **The guard must be securely attached to the power tool and positioned for maximum safety, so the least amount of wheel is exposed towards the operator.** The guard helps to protect operator from broken wheel fragments, accidental contact with wheel and sparks that could ignite clothing.
- **Wheels must be used only for recommended applications. For example: do not grind with the side of the cut-off wheel.** Abrasive cut-off wheels are intended for peripheral grinding; side forces applied to these wheels may cause them to shatter.
- **Always use undamaged wheel flanges that are of correct size and shape for your selected wheel.** Proper wheel flanges support the wheel thus reducing the possibility of wheel breakage. Flanges for cut-off wheels may be different from grinding wheel flanges.
- **Do not use worn down reinforced wheels from larger power tools.** Wheels intended for larger power tools are not suitable for the higher speed of a smaller tool and may burst.

ELECTRICAL CONNECTION

The network voltage must conform to the voltage indicated on the tool name plate. Under no circumstances should the tool be used when the power supply cable is damaged. A damaged cable must be replaced immediately by an authorized Customer Service Center. Do not try to repair the damaged cable yourself. The use of damaged power cables can lead to an electric shock.

WARNING: Never operate a damaged machine. Always tag a damaged machine and take it out of service until repairs can be made.

SAFETY SYMBOLS

CAUTION: Indicates a potentially hazardous situation, which, if not avoided may result in minor or moderate injury. It may also be used to alert against unsafe practices that may cause property damage.

DANGER: Indicates an imminently hazardous situation which if not avoided will result in death or

serious injury.

WARNING: Indicates a potentially hazardous situation which if not avoided will result in death or serious injury.

BEFORE USING THIS TOOL

WARNING: Some dust created by the power sanding, sawing, grinding, drilling and other construction activities contains chemicals known to cause cancer, birth defects or other reproductive harm. Some examples of these chemicals are:

- Lead from lead-bases paints
- Crystalline silica from bricks, cement and other masonry products
- Arsenic and chromium from chemically treated lumber.

Your risk from these exposures varies, depending on how often you do this type of work. To reduce your exposure to these chemicals, work in a well-ventilated area and work with approved safety equipment such as dust masks specially designed to filter out microscopic particles.

UNPACKING

Remove the tool and all loose parts from the carton. Place all parts on a secure, stationary work surface and look the machine over carefully.

LIST OF PARTS

List of Contents

Basic Assembly.....	1
Operator’s Manual.....	1
Lock Nut Wrench.....	1
Face Spanner Wrench.....	1
Flanges.....	2

RECOMMENDED ACCESSORIES

This machine may only be used with diamond cup wheels of its model specific diameter (see machine nameplate) with 22.23mm (7/8") arbor hole or with M14 female thread.All other uses are prohibited. Bonded abrasive accessories are not allowed to be used with this machine.

BASIC OPERATION



NOTE: Make sure that the power circuit voltage is the same as that shown on the specification plate of the machine and that switch is “OFF” before connecting the tool to the power circuit.

THE SWITCH

The machine has a lockable trigger switch. Squeeze the trigger to start the machine. To lock the switch on, press the lock button while holding the trigger switch on. To release, squeeze the trigger and release.

CAUTION: After the machine has been switched off, the spindle will continue rotating. Take care that parts of your body do not come into contact with the rotating parts or set the machine down while it is still rotating!

NOTE: This tool has anti-restart function. If the power supply is interrupted while the switch is locked on, when the power returns, the tool will not turn back on. In this case, the switch must first be turned off and then back on again.



HOW TO USE THE TOOL

Effective control of this machine requires **two-handed** operation for maximum protection and resistance to the start-up and operating torque. Place the work properly and hold the machine firmly **WITH BOTH HANDS** to prevent loss of control, which could cause personal injury. Protect your eyes from injury with safety glasses or goggles.

FRONT HANDLE

The front handle is adjustable. To adjust, loosen the knob, rotate to the desired angle and retighten. **Always ensure that the knob is tight before operating.**

OVERLOAD PROTECTION, OVERHEAT PROTECTION

Overload & Load Warning Lamp

When operating within the normal load range, the load warning lamp will glow green.

When full load is reached, the load warning lamp will flash red. If full load is exceeded and sustained for too long, the motor will shut down and the load warning lamp will glow solid red. In this case, the motor must be first shut off and then restarted. When this happens, the motor will very likely be near overheating, so it is also a good idea to run the motor at no load for a few minutes to cool it before continuing.



Overheat Thermal Protection

If the temperature of the motor gets too high, the thermal protection will shut the motor down. The switch must be first shut off and then restarted. When this happens, do not immediately start cutting after restarting the motor. Always run the machine at no load for a few minutes to return to a normal operating temperature

before continuing.

CAUTION: Whenever the machine overloads, always run the machine at no load for a few minutes to allow the temperature to return to normal before proceeding to work.

SPEED STABILIZATION

This machine is equipped with an electronic speed stabilization system which maintains constant speed under load.

VARIABLE SPEED FUNCTION

The motor's speed can be varied to suit the needs of different work situations. Turn the Variable Speed Thumbwheel clockwise to increase speed and anti-clockwise to decrease.



VACUUM CONNECTION

WARNING: Dust developing while working can be harmful to one's health.

This machine is designed specifically for dry grinding of concrete and similar materials. It uses dry diamond cup wheels and must be used with a suitable vacuum cleaner. Never exhaust the dust directly into the atmosphere.

To attach vacuum hose to Dust Port, hold machine firmly with one hand. Then with a twisting motion push the vacuum hose onto the Dust Port.


SAFETY GUARD

The Safety Guard (ie. the Skirt) must be used at all times when operating this machine. It is not adjustable. The Half-Moon Door may be temporarily removed to expose the Edge Cut-Out. See below.

THE EDGE CUT-OUT

When working against a wall or into a corner, the Skirt will prevent the grinding head from reaching all the way to the edge. To open, press the Tab, slide the Half-Moon Door outward to unlock, then rotate the Half-Moon Door to the side until it clicks.

NOTE: Keep the mechanism clean. Accumulated dust will make it difficult to open.



This will allow the Grinding Head to reach right up to the edge. Dust collection will not be ideal so close the door as soon as access to the Edge Cut-Out is no longer needed.

TOOL CHANGE – Removing and Replacing Diamond Cup Wheel


CAUTION: Before Working on or adjusting the machine, switch the machine “OFF” and UNPLUG machine from the socket.

CAUTION: The wheel can become very hot during the working process. Before replacing, allow the wheel to cool down


1. Place the machine on a level and sturdy workspace.
2. If using a diamond cup wheel with M14 female thread, do not use the flanges. Simply thread the wheel onto the spindle. Use the spindle lock button to keep the spindle from turning (rotate the spindle until the lock button engages) then tighten the wheel using the Face Spanner Wrench.
3. If using a diamond cup wheel with arbor hole, first mount the inner flange onto the spindle. Mount the wheel onto the shoulder of the Inner Flange, then thread on the Arbor Nut. Use the spindle lock button to keep the spindle from turning (rotate the spindle until the lock button engages) then tighten the Arbor Nut with the Lock Nut Wrench.
4. Replacement is the opposite of removal.

NOTE: For G180 models, the brush bristles of the dust skirt should stick out further than the cup wheel by roughly 2 to 5 mm. If the cup wheel is much shallower than the bristles, place one or two spacers between the spindle and the inner flange to achieve a suitable height of the cup wheel relative to the dust skirt.

INSTALLING DIAMOND CUP WHEELS



G125



G180

STORAGE

CAUTION: Do not store machine resting on its bristles – Store on its side.

CAUTION: Do not store machine with its power supply cable pinched. This will result in damage to the cable.

REPLACING DUST SKIRT BRUSHES

The dust skirt brushes may be replaced when worn. To replace, remove the 3 screws to replace the small brush on the half moon door and remove the 6 screws to replace the large brush on the dust skirt.

REPLACING CARBON BRUSHES

The carbon brushes are a normal wearing part and must be replaced when they reach their wear limit.

CAUTION: Always replace the brushes as a pair.

To replace:

Remove the screw on the hinged brush cover, then open it using the slot provided.

Using pliers, rotate the brush spring out of the way and slide old carbon brush out of the brush holder.

Unscrew the screw to remove the brush lead. The old carbon brush may now be lifted away.

Install a new brush. Installation is the reverse of removal.

Replace the motor tail cover.

NOTE: To reinstall the same brushes, first make sure the brushes go back in the way they came out. Otherwise a break-in period will occur that will reduce motor performance and increase brush wear. It is recommended that, at least once a year, you take the tool to an Authorized Service Center for a thorough cleaning and lubrication.

MAINTENANCE

WARNING: To reduce the risk of injury from unexpected starting or electrical shock, unplug the power cord before working on the machine.

Keep the tool clean. Remove accumulated dust from working parts. Make sure that the tool operates properly. Periodically check screws and bolts for tightness.

KEEPING TOOL CLEAN

Keep the machine and air inlet louver clean at all times to ensure correct and safe working. Under extreme application conditions involving metal, dust can enter the interior of the machine. The protective insulation of the machine can be adversely affected. In such cases the machine should be blown out regularly through the air inlet louver. It is recommended that a vacuum attachment be used.


WARNING: To ensure safety and reliability, all repairs, with the exception of externally accessible brushes, should be performed at an Authorized Service Center.

WARNING: If the replacement of the power supply cord is necessary, this has to be done by the manufacturer or their agent in order to avoid a safety hazard.

Do not throw electric power tools into the household waste! In accordance with the European Directive 2002/96/EG on Waste Electrical and Electronic Equipment and transposition into national law, used electric power tools must be collected separately and recycled in an environmentally friendly manner.



EXPLODED VIEW (G125 MODEL)




NO.01~88 Version 2024.08.06 D.966

PARTS LIST (G125 MODEL)

NO.	Parts Name	Q'TY	NO.	Parts Name	Q'TY
1	POWER SUPPLY CABLE (VDE-1.0x2Cx3M-H07RNF)	1	45	O-RING (Ø72x2)	1
2	CORD ARMOR	1	46	OIL SEAL (Ø15xØ24x5)	1
3	PANHEAD TAPPING SCREW (M4x14)	2	47	GEAR PLATE	1
4	CABLE CLIP	1	48	EXTERNAL CIRCLIP (S-17)	1
5	HANDLE HALF-RIGHT	1	49	BALL BEARING (6303)	1
6	CARBON CAP	2	50	SPRING WASHER (M4)	4
7	PANHEAD TAPPING SCREW (M4x12)	4	51	SOCKET CAP SCREW (M4x20xP0.7)	4
8	HANDLE HALF-LEFT	1	52	PARALLEL KEY (5x5x15)	1
9	PANHEAD TAPPING SCREW (M5x45)	4	53	SPINDLE (M14xP2.0-112.1MM)	1
10	PANHEAD TAPPING SCREW (M4x20)	7	54	OIL SEAL (Ø24xØ32x4)	1
11	THUMB WHEEL	1	56	SOCKET CAP SCREW (M4x10xP0.7)	4
12	RHEOSTAT	1	57	FLAT HEAD TAPPING SCREW (M4x10)	3
13	PANHEAD TAPPING SCREW (M4x30)	2	59	PANHEAD TAPPING SCREW (M4x14)	3
14	ELECTRONICS UNIT (220V)	1	60	HALF-MOON DOOR	1
15	BRUSH SPRING (0.4x4x3T)	2	61	SKIRT BRUSH-SMALL	1
16	CARBON BRUSH HOLDER (7x17)	2	62	SPRING (Ø0.55xØ4.9xØ6x15Lx6T)	4
18	PANHEAD MACHINE SCREW (M4x6xP0.7)	2	63	PANHEAD TAPPING SCREW (M4x10)	6
19	INSULATION PLATE (10x38x1)	2	64	DUST SKIRT	1
21	LED INDICATOR LIGHT	1	65	SKIRT BRUSH-SMALL	1
22	MOTOR HOUSING	1	66	SHOULDER BOLT (M4xP0.7x26L)	4
24	PANHEAD TAPPING SCREW (M5x70)	2	67	INNER FLANGE (Ø22.2-12.4mm)	1
25	PANHEAD MACHINE SCREW (M4x10xP0.7)	1	68	OUTER FLANGE (M14)	1
26	FLAT WASHER (Ø4xØ10x1)	1	69	HEX BOLT (M8x130xP1.25)	1
27	RUBBER WASHER (Ø4xØ11x1)	1	70	CLAMPING KNOB	1
28	PICKUP MAGNET (Ø8xØ15x5)	1	71	CLAMPING SLEEVE	2
29	SPACER (Ø8xØ12x10.5)	1	72	FRONT HANDLE	1
30	BALL BEARING (6200)	1	73	HEX NUT (M8)	1
31	ARMATURE (220V-81x46.4x55)	1	74	LOCK NUT WRENCH (30MM)	1
32	FAN BAFFLE	1	75	SPRING (Ø0.8 x Ø6.4 x Ø8 x 9T x 26L)	1
33	BALL BEARING (6201)	1	76	FACE SPANNER WRENCH (78MM)	1
34	OIL SEAL (Ø12xØ22x7)	1	78	BEARING PLATE	1
35	BEVEL PINION GEAR (M1.5x11T)	1	80	O-RING (Ø32x1.5)	1
36	GEAR HOUSING	1	82	SWITCH ACTUATOR (LOCK-ON)	1
37	SPINDLE LOCK BUTTON	1	83	PANHEAD TAPPING SCREW (M4x10)	4
38	SPRING (Ø0.9xØ7.4xØ9.2x5Tx16L)	2	84	PANHEAD TAPPING SCREW (M5x30)	4
39	ARBOR LOCK	1	85	COVER PANEL	1
40	O-RING (Ø5x1)	1	86	HALL EFFECT SWITCH	1
41	SPRING WASHER (M5)	4	87	STATOR (220V-81x46.4x55)	1
43	NEEDLE BEARING (HK 1010)	1	88	CARBON BRUSH (7x17x19)(220V)	2
44	BEVEL GEAR (M1.5x37T)	1			

EXPLODED VIEW (G180 MODEL)

NO.01~81 Version 2024.07.12 D.966



PARTS LIST (G180 MODEL)

NO.	Parts Name	Q'TY	NO.	Parts Name	Q'TY
1	POWER SUPPLY CABLE (VDE-1.5x2Cx3M-H07RNF)	1	40	GEAR HOUSING	1
2	CORD ARMOR	1	41	SPINDLE LOCK BUTTON	1
3	PANHEAD TAPPING SCREW (M4x14)	2	42	SPRING (Ø0.9xØ7.4xØ9.2x5Tx16L)	2
4	CABLE CLIP	1	43	ARBOR LOCK	1
5	HANDLE HALF-RIGHT	1	44	O-RING (Ø5x1)	1
6	CARBON CAP	2	47	NEEDLE BEARING (HK 1010)	1
7	PANHEAD TAPPING SCREW (M4x12)	4	48	BEVEL GEAR (M1.5x43T)	1
8	HANDLE HALF-LEFT	1	49	O-RING (Ø72x2)	1
9	PANHEAD TAPPING SCREW (M5x45)	8	50	OIL SEAL (Ø15xØ24x5)	1
10	PANHEAD TAPPING SCREW (M4x20)	7	51	GEAR PLATE	1
11	THUMB WHEEL	1	52	EXTERNAL CIRCLIP (S-17)	1
12	RHEOSTAT	1	53	BALL BEARING (6303)	1
13	PANHEAD TAPPING SCREW (M4x30)	2	54	SPRING WASHER (M4)	4
14	ELECTRONICS UNIT (110V/220V)	1	55	SOCKET CAP SCREW (M4x20xP0.7)	4
15	BRUSH SPRING (0.4x4x3T)	2	56	PARALLEL KEY (5x5x15)	1
16	CARBON BRUSH HOLDER (7x17)	2	57	SPINDLE (M14xP2.0-124.1MM)	1
17	CARBON BRUSH (7x17x19)(110V/220V)	2	58	OIL SEAL (Ø24xØ32x4)	1
18	PANHEAD MACHINE SCREW (M4x6xP0.7)	2	59	BEARING PLATE	1
19	INSULATION PLATE (10x38x1)	2	60	SOCKET CAP SCREW (M4x10xP0.7)	4
20	PANHEAD TAPPING SCREW-B (M4x10)	4	61	FLAT HEAD TAPPING SCREW (M4x10)	3
21	SWITCH ACTUATOR (LOCK-ON)	1	62	COVER PANEL	1
22	SPRING (Ø0.8 x Ø6.4 x Ø8 x 9T x 26L)	1	63	HALF-MOON DOOR	1
23	LED INDICATOR LIGHT	1	64	SKIRT BRUSH-SMALL	1
24	HALL EFFECT SWITCH	1	65	SPRING (Ø0.55xØ4.9xØ6x15Lx6T)	4
25	MOTOR HOUSING	1	67	DUST SKIRT	1
26	STATOR (110V/220V-81x46.4x70)	1	68	SKIRT BRUSH-LARGE	1
27	PANHEAD TAPPING SCREW (M5x85)	2	69	SHOULDER BOLT (M4xP0.7x26L)	4
28	PANHEAD MACHINE SCREW (M4x10xP0.7)	1	70	INNER FLANGE (Ø22.2-12.4mm)	1
29	FLAT WASHER (Ø4xØ10x1)	1	71	OUTER FLANGE (M14)	1
30	RUBBER WASHER (Ø4xØ11x1)	1	72	HEX BOLT (M8x130xP1.25)	1
31	PICKUP MAGNET (Ø8xØ15x5)	1	73	CLAMPING KNOB	1
32	SPACER (Ø8xØ12x10.5)	1	74	CLAMPING SLEEVE	2
33	BALL BEARING (6200)	1	75	FRONT HANDLE	1
34	ARMATURE (110V/220V-81x46.4x70)	1	76	HEX NUT (M8)	1
35	FAN BAFFLE	1	77	LOCK NUT WRENCH (30MM)	1
36	BALL BEARING (6201)	1	79	PANHEAD TAPPING SCREW (M4x16)	9
37	O-RING (Ø32x1.5)	1	80	SPACER	2
38	OIL SEAL (Ø12xØ22x7)	1	81	FACE SPANNER WRENCH (93MM)	1
39	BEVEL PINION GEAR (M1.5x10T)	1	78	7" DIAMOND CUP WHEEL (7/8" BORE)	1

Noise/vibration information

Measured in accordance with EN 60745-2-3 (G125) & EN 62841-1:2015 (G180)

Model no. : G125

Noise level: Sound pressure level(L_{pA}): 90.5 dB(A) Sound power level(L_{wA}): 101.5 dB(A) $K=3.0$ dB

Vibration level: $a_h=4.1$ m/s² $K=1.5$ m/s² (Sanding stone)

Model no. : G180

Noise level: Sound pressure level(L_{pA}): 90.5 dB(A) Sound power level(L_{wA}): 101.5 dB(A) $K=3.0$ dB

Vibration level: $a_h=6.1$ m/s² $K=1.5$ m/s² (grinding concrete)

The vibration emission level has been measured in accordance with a standardised test given in EN 60745 & EN 62841 ; it may be used to compare one tool with another and as a preliminary assessment of exposure to vibration when using the tool for the applications mentioned

- using the tool for different applications, or with different or poorly maintained accessories, may significantly increase the exposure level
- the times when the tool is switched off or when it is running but not actually doing the job, may significantly reduce the exposure level

protect yourself against the effects of vibration by maintaining the tool and its accessories, keeping your hands warm, and organizing your work patterns

CE Declaration of Conformity

•We declare under our sole responsibility that this product is in conformity with the following standards or standardized documents: EN 60745-1: 2009 + A11: 2010; EN 60745-2-3: 2011 + A2:2013+A11:2014+A12:2014 +A13:2015 EN 61000, EN 55014 in accordance with the regulations 2014/30/EU, 2006/42/EC, 2011/65/EU

•Technical file at: LEE YEONG INDUSTRIAL CO., LTD., NO.2, KEJIA RD., DOULIU CITY,
YUNLIN COUNTY 64057, TAIWAN

You-Chun, Liu
Operation & Engineering

You chun Liu

Chih-Hao, Lai
Approval Manager

chih hao lai

LEE YEONG INDUSTRIAL CO., LTD.,
NO.2, KEJIA RD., DOULIU CITY, YUNLIN COUNTY 64057, TAIWAN

05.26.2020

LEE YEONG INDUSTRIAL CO., LTD.

NO.2, KEJIA RD., DOULIU CITY,
YUNLIN COUNTY 64057, TAIWAN

TEL: 886-5-5518689 (REP)

Fax: 886-5-5518635

