

## PROFILE OF REPORTS

Date: July 17, 2017

Replaces: July 13, 2017

Master Contract: 215310

Main File: Vancouver

File No:215310

Submittor:

(Contact: 4570094)

Lee Yeong Industrial Co., Ltd.

No.2, Kejia Rd. Douliu City

Yunlin County 64057

Taiwan

Attn: Mr. Mike Jiang

Tel: (886) 5-5518689, Ext. 120

Fax: (886) 5-5518635

Email: mike@agp-powertools.com

Factories:

Name & Address ID No

Inspection File No./Factory Office: Contract No

4570094 Lee Yeong Industrial Co., Ltd. CSA Taiwan 215576

No.2, Kejia Rd. F1

Douliu City

Yunlin County 64057

Taiwan

Factory ID No. Subject Report Project

1311435 May 3, 2002 - Reinstatement of Certification of Ed. 1

Product previously certified under legacy file 105847 and transfer to new Master Contact

215310.

June 18, 2003 - Multiple Listing for Hitech 1321684 Services Ltd.', Models ME3500, ME5000, ALY-Ed. 1

35, MAX38, AME3500, AME5000 and

MAX38A. (C/US)

Transferred from legacy file LR 105847 to new

Master Contract 215310.

1312195 June 19, 2002 - 35 mm Magnetic Drill Presses, Ed. 1

Model LY-35, ME3500, ME5000, ALY-25,

MD150, ALY-35, MAX38, AME3500,

AME5000, MAX38A, AT-35, ME3000AUTO. AB32, MAX30AUTO, IBM32-A, MBD3500, HAND-Mag, MDM36, EV3500 and UNI3000. (In compliance with CSA-C22.2 No. 745-1-

95/UL Std No. 745-1-1st Edition and CSA-C22.2

No. 745-2-32-95/UL Std No. 745-2-32-1st

			Edition.)
	1350228 Ed. 2		May 19, 2008 - Update to Report 1312195 to include Models AT-35, ME3000AUTO, AB32, MAX30AUTO, IBM32-A, MDB3500, HAND-Mag, MDM36, EV3500 and UNI3000.
	2541160 Ed. 3		August 2, 2012 - Update to Report 1312195 to add Model MD150.
1517444 Ed. 1		F1	July 8, 2004 - Magnetic Drill Presses, Models ME7500 4 speed, NB 7500, BEAR 300, Max 7500, ME5000 2 speed, NB 5000, COUGAR 200, Max 5000, MD250, ME7500/4, ME75, ME754, ME75/50, ME75/4 speed, EBO7500/4, 592582, EVOMAG75, ME75002EU, 7500 ForatriceMagnetica, ME5000/2, ME50, ME50/7, ME50/2 speed, EBO5000/2, 592581, EVOMAG50, ME5000X2EU. In compliance with CSA-C22.2 No. 745-1-95 / UL Std No. 745-1-2nd Edition and CSA-C22.2 No. 745-2-32-1st Edition)
	2541161 Ed. 2		August 3, 2012 - Update to Report 1517444 to add Model MD250.
	70019726 Ed. 3		February 3, 2015 â€" Update to report 1517444 to add Models ME7500/4, ME75, ME754, ME75/50, ME75/4 speed, EBO7500/4, 592582, EVOMAG75, ME75002EU, 7500 ForatriceMagnetica, ME5000/2, ME50, ME50/75, ME50/2 speed, EBO5000/2, 592581, EVOMAG50, ME5000X2EU and alternate construction.
1517446 Ed. 1		F1	March 3, 2005 - Metal cutting circular saws, Models CS230, EDC09, MCS230, ROTA SPEED 230, CS200, MCS200 and ROTA SPEED 200. (In compliance with CSA-C22.2 No.60745-1- 04/UL Std No. 60745-1-3rd Edition and CSA- C22.2 No. 60745-2-5-04/UL Std No. 60745-2-5- 3rd Edition)
	2541159 Ed. 2		August 3, 2012 - Updated to report 1517446 to add Model EDC09.
1712694 Ed. 1		F1	November 3, 2005 - Electric mixers, Models EV32, EV32B, EV800, EV800B, EMX800, EMX800B, EHR080, EHR080B, 84-MIX, ROTAMIX800, ROTO800, 800IHR, MALAX8, EV42, EV42B, EV1100, EV1100B, EMX1100, EMX1100B, EHR110EL, EHR110BEL, PI-MX1100, ROTAMIX1100, ROTO1100, 1100IHR, MALAX11, EV52, EV52B, EV1300, EV1300B, EMX1300, EMX1300B, EHR130EL, EHR130BEL, PI-MX1300, ROTAMIX1300, ROTO1300, 1300IHR, MALAX13. (C/US)

2304045 Ed. 1		F1	August 4, 2010 - Magnetic Drill Presses, cord-connected, grounded, Models AC50, SMA351H, SMA351L, SMA352, SMA502, SMD351H, SMD351L, SMD352, SMD502, 39D731 and 39D742.  - In compliance with CSA-C22.2 No. 745-1-
			95/UL Std No. 745-1-2nd Edition and CSA-C22.2 No. 745-2-32-95/UL Std No. 745-2-32-1st Edition.
	2343131 Ed. 2		September 6, 2010 - Update to Report 2304045 to add Models 39D731 and 39D742.
	2468776 Ed. 3		November 14, 2011 - Updated to Report 2304045 to add Models SMD351H, SMD351L, SMD352 and SMD502.
	2541162 Ed. 4		August 3, 2012 - Update to Report 2304045 to add Model AC50.
2370873 Ed. 1	-	F1	March 25, 2011 - Magnetic Drill Press, cord-connected, grounded, Model PMD3530In compliance with CSA-C22.2 No.745-1-95/UL Std No. 745-1-2 <sup>nd</sup> Edition and CSA-C22.2 No. 745-2-32-95/UL Std No. 745-2-32-1 <sup>st</sup> Edition.
-	-	-	February 13, 2012 - Client Services Center (mgm) - Changed Contact Person from Mr. Daive Shieh, President to Mr. Larry Yang
-	-	-	February 13, 2012 - Client Services Center (mgm) - Submittor Address Change and Factory Relocation: From: No. 29 Fu-Hsing Rd, Tou-Liu City Industrial Zone, Yun Lin Hsien, Taiwan To: No.2, Kejia Rd., Douliu City, Yunlin County 64057, Taiwan
2605638 Ed. 1			July 15, 2013 - Circular Saw, 320mm, cord-connected, double-insulated, Models CS320, SHD8320, MT320. (CSA 60745-1-07/UL 60745-1-4th; CSA 60745-2-5-07/UL 60745-2-5-4th)
2590958 Ed. 1		F1	July 31, 2013 - Dry-Cut Metal Saws, cord-connected, grounded, Models DRC355 and EDC14 In compliance with C22.2 No. 71.2-10 and UL 987-8th Edition - WMTC Annual Surveillance Assessment
2656066 Ed. 1		F1	October 1, 2013 – Rotary tool, cord-connected, double-insulated, Model 9100In compliance with CSA-C22.2 No. 60745-1-07/UL Std No. 60745-1-4th Edition, CSA-C22.2 No. 60745-2-23-13/UL Std No. 745-2-23-1st Edition
	70085835 Ed.2	-	August 24, 2016 - Update to Report 2656066 to upgrade part 2 standard from CAN/CSA-C22.2

			No. 745-2-36-95 (R2009) (UL 745-2-36, 1st Edition) to CAN/CSA-C22.2 No. 60745-2-23-13- (UL 60745-2-23, 1st Edition)
2696216M		-	February 10, 2014 - Multiple Listing for "Jepson Power GmbH' for Circular Saw Model SHDC8320.  (Alternate File 260165) (Form B)
2731742 Ed. 1			July 10, 2014 - Magnetic Drill Press, cord- connected, grounded, Models DWE1622 and DWE1622K. -In compliance with CSA-C22.2 No.745-1-95/UL Std No. 745-1-2nd Edition and CSA-C22.2 No. 745-2-32-95/UL Std No. 745-2-32-1st Edition
	70042665 Ed. 2		September 17, 2015 – Update to report 2731742 to add alternate motor enclosure material.
2701169 Ed. 1			March 4, 2014 - Diamond Core Drill, cord connected, grounded Models DM6D, CD160D, CD6D, DM63D, HCD36, DM6P, CD160P, CD6P, DM63P, DMC6D, DMC160D, DMC63D, DMC6P, DMC160P, DMC63P. (CSA 60745-1-07/UL 60745-1-4th; CSA 60745-2-1-04 with AMD 1/UL 60745-2-1-2 <sup>nd</sup> with AMD 1)
	70121716 Ed. 2		April 13, 2017 - Update report 2701169 to correct the current rating.
2767522 Ed. 1		F1	October 31, 2014 - Concrete Saws, cord-connected, grounded, Models C14, CS14, C355, CS355, SC14, SCS14, SC355 and SCS355In compliance with CSA-C22.2 No. 60745-1-07 (Upd.3) / UL Std No. 60745-1-4th Edition, CSA-C22.2 No. 60745-2-22-12 (Upd.1) / UL Std No. 60745-2-22-1st EditionWMTC Annual Surveillance Assessment
70099540 Ed.1	-	All	November 16, 2016 - Wrap-around Tube Sander (Belt Sander)/ Drum Polisher (Polisher), cord-connected, double-insulated Models WS760, 30-A 285,RSM760, 495050D,MR-760.1500, EDXE20, WS30, PS1001, PÃ□SOVEC 40V, 311-TK (CSA 60745-1-07 3rd edition/UL 60745-1-4th; CSA 60745-2-4-04 2nd edition/UL 60745-2-1-4 2nd edition)
70126793 Ed.1	-	-	June 28, 2017 - Tapper, cord-connected, double-insulated. Model T14; T16; PT14; ET14; T1416; PT1416; ET1416; 3860014; GSMPRO, rated 115Vac, 3.9A, 60Hz, FWD:280/REV:680 n0/min.
			(CSA 60745-2-9-04 2nd editionA1/UL 60745-2-9 2nd edition in conjunction with CSA 60745-1-07 3rd edition/UL 60745-1-4th) -
	70147051		July 17, 2017 - Update report 70126793 to

Ed.2 include alternate new models name XLT
TAPPER and GS18 and T18 are identical with
T14 except the model difference.

- July 13, 2017 - Client Services Center - Changed
Contact Person from Larry Yang to Mike Jiang.